CribMaster

Scan from anywhere.

POU
Point of Use System

The portable desktop computer and scanner turn any space into a workstation, allowing you to manage your inventory closer to the tool crib.

Features & Benefits

- Desktop computer and scanner allow CribMaster software to run closer to the tool crib

- Portable screen and scanner can turn any table top into a workstation

- Ideal introductory solution to CribMaster software

- Includes barcode or prox card reader for authentication

- Includes keyboard for accessing and running software

Accessories

- Can upgrade to a Bluetooth® scanner for increased mobility within the tool crib

Suggested Inventory Items

POU can scan and manage any item within the tool crib, from consumable to durable items.

- Hand tools
- Power tools
- PPE items
- Spare parts
- Inserts
- Facemills

POU Specs

Exterior Dimensions		
Height	10.3 in	26.2 cm
Width	12.7 in	32.3 cm
Depth	2.2 in	5.6 cm

Weight	
5.5 lbs	2.5 kg

Power Requirements		
Device Type	Power Adapter	
Watts	.65 kW	.752 kW

Operating Environment		
Temperature	41-95° F	0-35° C
Humidity	20% to 80% (no condensation)	

Operating System Options
Windows 10

Software Features
CribMaster Client version 10 and higher